

SAFETY DIRECTIVE

Replacement of pressure side fuel hose at fuel pump MANDATORY

Symbols:

Please pay special attention to the following symbols emphasizing particular information throughout this document.

- ▲ WARNING: Identifies an instruction, which if not followed, may cause serious injury or even death.
- ◆ CAUTION: Denotes an instruction, which if not followed, may severely damage the aircraft or could lead to suspension of factory warranty.
- **★** NOTE: Information useful to implement the change more easily.

1. General

<u>Issued bv:</u> Powrachute, LLC. 3001 West Airport Road, Hastings, MI 49058

Web: <u>www.powrachute.com</u> Ph: 574-286-9670 In conjunction with Rotax Alert ASB-912-061UL R1

Release Date: June 06, 2012

<u>Date of Effect:</u> Immediately

<u>Compliance:</u> Before Next Flight

Release Number: 06-06-12-4

Superseded Notice: None

Models Effected: Airwolf 912ULS with engine serial numbers matching Rotax ASB-912-061UL R1

Affected S/N: See engine serial numbers in Rotax ASB-912-061UL R1

Reason: Contaminated fuel delivery

2. Material Information

Must purchase approved parts required per Rotax ASB-912-061UL R1

3. Compliance

<u>License required:</u> For Inspection, Owner or Pilot In Command

For Replacement on S-LSA:

LSA Repairman, A&P Mechanic, Part 145 Repair Station or Owner.

<u>Certification:</u> Sign off aircraft logbook when replacement has been made and by an

authorized person defined above.

This Service Bulletin serves as a Letter of Authorization (LOA) and is valid

without being signed and without any additional paperwork.

★ NOTE: Do not forget to log in the aircraft logbook.

4. Instructions for Inspection

Check to see if your serial number on the front of your engine matches any in Rotax ASB-912-061UL R1

5. Instructions for Replacement

Follow procedures outlined in Rotax ASB-912-061UL R1

6. Advise

In case of contaminations of the float chambers first the cause must be found and the relevant measures need to be taken. Possibly the whole fuel system including carburetors needs to be cleaned and checked.